

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

March 1, 2011

Mr. Ed Peresie Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

Pittsburgh, PA 15222-4745

Mr. Steve Hepler Southwest Region 400 Waterfront Drive

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

A . 18 m

Subject: USS Reference Number: 11-0065

ACHD Reference Number: N/A #2 Battery Igniter Flare USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the outage. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

James F. Dudek Plant Manager Clairton Works

RECEIVED MAR 0 8 2011

3AP20

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- 1. USS Reference Number: 11-0065 ACHD Reference Number: N/A
- 2. Date & Time of Breakdown: Date: 02/27/11 Time: 0600 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: #2 Battery Igniter Flare
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: The #2 Battery Igniter Flare was unavailable while repairs were made to the pusher side and coke side bleeder stack power supplies.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 No environmental impact.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A
 - C. Amount of each type emitted (or likely to be emitted). N/A
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The repairs were completed and the igniter flares were available for service.
- 10. Facility back in operation Date: 02/27/11 Time: 0910 hours

Signature (ilen) h. Davis Date 3-1-11

Senior Environmental Control Engineer Phone: 412-233-1015